TO: John R. Martin, Chief Fire Marshal, Springfield, Missouri

RE: Gasoline Spill at 928 East Kearney, Springfield, Missouri, January 6, 1976, 0947 Hours, Run #45

This alarm was answered by pumper #4 and Battalion Chief, Howard Thurman.

The incident occurred at a service station at 928 East Kearney, owned by Mr. Ed Groves, 2340 North East Avenue, Springfield, Missouri. The station was operated by Mr. Dave Hampton, address is not available at this time.

The incident occurred when a transport truck owned by Transport Delivery Company of Tulsa, Oklahoma, based at Mt. Vernon, Missouri. at the Ellex Terminal, phone number 466-3424, and driven by Austin Brown, R. R. 1, Springfield, Missouri, was filling an underground tank at the service station when it flowed over spilling gasoline into the driveway. There was approximately 35 to 50 gallons spilled estimated by Battalion Chief, Howard Thurman. Upon receipt of the alarm from truck driver, Mr. Austin Brown, the Springfield Fire Department dispatcher dispatched pumper #4 and Battalion Chief. Howard Thurman, and contacted the Environmental Protection Agency. Pumper #4 then responded to the scene and determined that it was a definite fire hazard. They then began to take proper steps to eliminate sources of ignition at the scene by shutting off the natural gas to the meters of the rug company which is west of the service station and to the service station itself. Fire hydrant line was then laid across Kearney from the northeast corner of East Avenue and Kearney. Captain Richard Mann, #4 station then requested traffic assistance from the Springfield Police Department. By this time Battalion Chief, Howard Thurman, had arrived on the scene and assisted in setting up operations in the emergency. Feeling there was eminent fire danger, flushing operations were begun to flush flammable liquid from beneath the truck and away from the buildings at this location.

Using a $2\frac{1}{2}$ " combination nozzle with approximately a 50# plug pressure it is estimated that approximately 1,500 gallons of water was used in the flushing operations by flushing for 10 to 12 minutes. Flushing operations ceased when the street had been cleared enough to eliminate what was considered by Battalion Chief, Howard Thurman, as a fire hazard. Mr. Criswell from the Environmental Protection Agency had arrived at this time and began preparations to set up a catch basin for what had been flushed away.

Pumper #4 then returned to #4 fire station to await a further call from the Environmental Protection Agency to return to the scene for any additional flushing which would be needed. Pumper #4 was then returned to the scene to further flush water into Kearney Street from a plug connection. At this time approximately 3,000 gallons was flushed into the street from the open plug connection into the catch basin which had been set up by the EPA. When this flushing operation was completed, pumper #4 returned back to service at III9 hours.

Gas Spill, 928 E. Kearney January 7, 1976 Page 2 (Cont.)

Before leaving the scene Captain Richard Mann, #4 fire station, contacted the driver of the vehicle and asked what happened to cause the spill, driver related that he had been inside the station watching the pumping operation when gas began to squirt from around the nozzle. He then ran to the truck and turned off his pump and called the Spring-field Fire Department.

At this time there is nothing further to report, so this report is closed.

Respectfully submitted,

Herschel A. Jordan, Fire Marshal Springfield Fire Prevention Bureau

HAJ/nvc

FIRE DEPARTMENT INCIDENT REPORT

Location of alarm response (street and number) 929 E KEAPNEN						
Company No. 4 Captain R.L. Mann Report No. 45						
Shift: A B C District 4 Battalion Chief Thur and Other						
Date: Day of Week TUES Month JAN Day 6 Year 1976 Time Alarm Rec d. 547						
Alarm from: Alarm Dispatcher N Box No. Other (describe)						
Company No reported to cover Company Noathours, on authority of						
Returned to quarters hours, authority of						
Back in service // / 9 hours.						
Type occupancy: Residential Business Hotel Motel Apts. Other Ser. STM.						
Classifi Fire in Building Rescue, MCCU, Ambulance						
cation of Fire in Grass or Brush Service Calls						
Check the Fire in Rubbish near Bldg. Smoke, Steam Scare, Other Gas Sill						
Proper Fire in Dump False Alarm						
Other Fire Outdoors Accidental Alarm, Malfunction, Other						
Fire in Vehicle in Street Set by Children Other						
Automobile Special Assignment Gara Sill						
Truck iolation of Fire Code						
Bus Loss of Life or Injury						
Other Describe in Remarks						
If vehicle on fire in a bldg., report as bldg. fire, describe in remarks						
Fire in Vehicle in Street: Owner & Address						
Name of Driver Make Year Lic. No.						
Probable Cause and Damage						
How Extinguished Pumper Used Pump Time						
Out on Arrival Weather: Temp 39° Wind: Direction 55 Velocity 20						
Estimated Damage: \$1 to \$50Other Amount Specify						
Loss of Life Injury Members Citizen Names details						
Loss of Life Injury Members Citizen Names, details						
Loss of Life Injury Members Citizen Names, details						
If additional space is needed, see "Remarks" at end of report or attach separate sheet. REPORT OF FIRE IN BUILDING						
If additional space is needed, see "Remarks" at end of report or attach separate sheet.						
If additional space is needed, see "Remarks" at end of report or attach separate sheet. REPORT OF FIRE IN BUILDING Height (stories)Construction (fire resistive), brick-joist, frame, etc						
If additional space is needed, see "Remarks" at end of report or attach separate sheet. REPORT OF FIRE IN BUILDING Height (stories)Construction (fire resistive), brick-joist, frame, etc. Walls (brick, brick veneer, frame, metal, etc.)Partit ons (frame,						
If additional space is needed, see "Remarks" at end of report or attach separate sheet. REPORT OF FIRE IN BUILDING Height (stories)Construction (fire resistive), brick-joist, frame, etc. Walls (brick, brick veneer, frame, metal, etc.)Partitions (frame, metal, blocks, plastered, etc.)Floor construction (bes. light fire						
If additional space is needed, see "Remarks" at end of report or attach separate sheet. REPORT OF FIRE IN BUILDING Height (stories)Construction (fire resistive), brick-joist, frame, etc. Walls (brick, brick veneer, frame, metal, etc.)Partitions (frame, metal, blocks, plastered, etc.)Floor construction (bes. light fire						
If additional space is needed, see "Remarks" at end of report or attach separate sheet. REPORT OF FIRE IN BUILDING Height (stories)Construction (fire resistive), brick-joist, frame, etc Walls (brick, brick veneer, frame, metal, etc.)Partit ons (frame, metal, blocks, plastered, etc.)Floor construction (her light, fire resistive, wood joist, steel joist, etc.) Roof (shingle, tar and gravel, built-up, etc.)roof joists (wood,						
If additional space is needed, see "Remarks" at end of report or attach separate sheet. REPORT OF FIRE IN BUILDING Height (stories)Construction (fire resistive), brick-joist, frame, etc Walls (brick, brick veneer, frame, metal, etc.)Partitions (frame, metal, blocks, plastered, etc.)Floor construction (her light, fire resistive, wood joist, steel joist, etc.)						

Probable cause (in detail)_	y				
Area of origin					
Loss of life Injury	F.D. Member Citiz	en Name,	detail		
Type material ignited: Clot	hing, wood, paper, fa	bric, gasoli	ne, chemic	als, beddi	ng, L.P. gas,
natural gas, fat or grease,					
plies, paint, varnish, rug,					
Form of heat of ignition: S					
down, cutting and welding, b					
tric lamp, pilot light, fire					
Extent of flame damage (desc				And the second second second	and the second s
Confined to part of room or				The state of the s	
floor or "fire area" of orig				the same of the sa	
of origin Comments:					your barrering
Extent of other damage (desc				nting to da	maged area):
Comments:			,		
•					
Flame spread factors: Sprea	d on ceiling Wall	☐ Floor □	Ceiling	and wall	Ceiling .
and floor Wall and floor					
stairwell					
throughs, etc. Comments:					, i po pono
Horizontal spread: Air duct	THE RESERVE OF THE PERSON NAMED IN COLUMN 2 IN COLUMN				Corridors 🗍
Utility openings Windows			The second secon	The second secon	
Gravity (fell on, etc.)				, L	
Other companies responding					
Chief Officers at fire					
Total men responding 4 0	n-duty men 4 Off-d	uty men	Fire Mars	shal reques	ted
Name (F.M.)					No. of the Assessment of the Control
Spontaneous ignition Inc					
Owner of building Ed G.			the street of th	TAU	6
Occupant DAVE HAMPTA					
Loss on building - Est					
Insurance on building					
Method of Extinguishment:					
Pumping time	No. Streams	<u> </u>	2111	Over	Ft. of
				2111	Ladders
REMARKS: A Transport	- Truck , 2	T	a. T	Dal.	
IN OKLA. DrivEN	B. 1 -	Dans	PAOL.	, C L .	very
3	TO TUSTON	Brown	BR1	5,00:44	7:461

REMARKS: A Transport Truck of Truesport Delivery Co Tulsa OKLA. Driver By Auston Brown RRI Spring?: eld. Was filling underground Tonk when it over Flowed Spilling Approx 35 To 50 sals. WE used A plug Line To Flosh Aren.